

CROSBY KC ADAPTER 5-2 (MODEL 118)

3/14/55

(0.1)

1. C-100B DOESN'T EXIST IN CIRCUIT. TRIAL INSTALLATION PROVES OF NO VALUE.

2. ALIGNMENT INSTRUCTIONS C-2, 3, 5, 7 COULD BE DELETED; AT 0.2 VOLTS INPUT THERE IS INSUFFICIENT SIGNAL TO GIVE VTVM INDICATION ON PIN-2 OF V106; CARRIER METER MAY BE USED VERY SATISFACTORILY.

3. FOUND UNSOLDERED VOLTAGE AT ONE END OF R-111

LINE
MULTIMETER
K.V.

IP.A. I₉

PA I₉

IP.A. I₉

K.V.

MOD I₉

$$R = \frac{E}{I} =$$

2.0
0.05
100